

AN INTRODUCTION IN PENSTOCKS

OPERATION:

LOCAL AND REMOTE WITH NON RISING SPINDLE

remote operation 2 3 5 6 7 Operation keys Floor column Floor column Eccentric Floor column Handwheel Actuator or with bevelgearbox floor column with with handwheel T-key bevelgearbox on wall bracket with actuator Large Small handwheel handwheel Conical square Socket with keyway Coupling Extension Guide bracket direct on frame 2 3 4 Operation keys T-key Handwheel Actuator Bevelgearbox with console with handwheel and console Conical square socket Socket with keyway